


Recovered From: WTC 5, Floor undetermined**Failure Mode:** Column buckling due to heat exposure

Figure 4-22 Connection samples (continued).

On the lower floors, the steel beams appeared to have heat damage from direct fire impact and there was little or no evidence of shop painting, indicating that fireproofing material was either missing before the fire or delaminated early in the fire exposure.

In general, the buildings responded as expected to the impact loadings. Collapse was often localized, although half of WTC 4 and most of the central part of WTC 6 suffered collapse on all floors. The damage was consistent with the observed impact load.

Reinforced web openings in steel beams performed well, as no damage or local buckling was observed at these locations.

The automatic sprinkler system did not control the fires. Some sprinkler heads fused, but there was no evidence of significant water damage, due to a lack of water. This is consistent with the lack of water damage in the bookstore on the lower level and the complete burnout of the upper floors.

4.5 Recommendations

The scope of this study and the limited time allotted prevented in-depth study of many issues that should be explored before final conclusions are reached. Additional studies of the performance of WTC 4, 5, and 6 during the events of September 11, 2001, and related building performance issues should be conducted. These include the following:

- There is insufficient understanding of the performance of connections and their adequacy under real fire exposures as discussed in Appendix A. This is an area that needs further study. The samples discussed in Section 4.3.2 should be useful in such a study.
- A determination of the combined structural and fire properties of the critical structural connections should be made to permit prediction of their behavior under overload conditions. This can be accomplished with a combination of thermal transfer modeling, structural finite element modeling (FEM), and full-scale physical testing.