



Figure 5–105.
Cropped photograph
showing the west face
of WTC 7, shot at
11:13:51 a.m. from
New Jersey looking
across the Hudson
River.

The intensity levels
have been adjusted.

Visual evidence indicates that the smoke plumes seen in Figure 5–104 and Figure 5–105 originated from vehicles that were ignited at numerous locations following the collapse of WTC 1. Several burned out vehicles can be seen on West Broadway between the east side of WTC 7 and the Post Office Building in Figure 5–90. Review of several photographs showed that there were at least six burned automobiles, two postal trucks, and a fire truck on this single block. Another view of West Broadway taken from one block further north near its corner with Park Place is shown in Figure 5–106. Multiple burned vehicles, including a bus, several cars, and trucks, are visible on the street between Park Place and Barclay Street. A second photograph taken much earlier from a location slightly closer to Barclay Street is shown Figure 5–107. In addition to the vehicles visible in these two images, other photographs of the area show that there were several additional burned out automobiles closer to Barclay Street. Nearly every vehicle on this block was ignited.