



Figure A-4. Northwest corner of the Con Edison substation (building on left), showing light damage from WTC 1 debris. (Photo taken sometime in the afternoon on Sept. 11, 2001.)

George Miller/NYCTA

Figure A-5 shows another view of the Con Edison portion of WTC 7, shot from a police helicopter at about 3:00 p.m. Fires can be seen on the 7th and 12th floors of WTC 7. Light debris is visible on the grill work which formed the roof of the north portion of the Con Edison substation; this portion of the Con Edison substation appears to be intact, with no visible evidence of smoke. No photograph, video record, or witness account gathered during the investigation identified smoke or flames originating from the Con Edison portion of WTC 7.

The collapse of WTC 7 buried the Con Edison structure and all the equipment in it. Figure A-6 shows the collapsed building at the beginning of the salvage and clean up operations, viewed looking south from Greenwich Street.




Figure A-5. Aerial view of the middle of the north side of the Con Edison substation, taken at 2:57 p.m. ± 5 min on September 11, 2001.

Source: NYPD Aviation unit photo, 2-50 #21