



Figure A-8.
Photograph taken
in mid-October,
2001, showing
Con Edison
transformers #6
and #1 uncovered
from debris pile of
WTC 7.

Source: G&S Technologies, reproduced with permission

Transformer #7 (or possibly #5) is barely visible within the white box in Figure A-9. This transformer and the other three depicted in Figures A-7 and A-8 were not salvageable and were discarded.

NIST was unable to determine whether the thermal damage to the transformers occurred due to electrical overheating, due to a fire in the substation after the SCADA logs were terminated around 4:33 p.m., or due to burning within the rubble pile subsequent to the collapse of WTC 7.



Figure A-9.
Con Edison
transformer #7
(or #5) uncovered
from debris pile of
WTC 7; photo
taken mid-
October, 2001.

Source: G&S Technologies, reproduced with permission